


PUSHBUTTONS—Total number — 6, arranged in one row, using round pushbuttons. The purpose of —3 button is to allow the radio or phono to be silenced while answering the telephone etc. It can be turned on instantly by depressing buttons —1 or —2. This avoids readjustment of the level control or waiting for the set to heat up again.

1 2 3 4 5 6 Phonograph Radio Silent B.C. S.W. 1 S.W. 2 Band 11.5-23 mc/s 5.8-12 mc/s.

## Northern Electric 7002 Alignment, Chassis Layout, & Push Button Tuning



Model 7002 Chassis Wiring

## **REALIGNING DETAILS**

Alignment Procedure should be carried out according to the following table and in the order shown:

Generator Frequency		Dummy Antenna	Receiver Connection	Control Setting	Item to be Adjusted For Max. Output
1.	455 kc	.1 mfd.	Pin No. 8 6SA7	Manual B.C. Gang Open	Iron cores on T6 & T7. Located at each end of coil shield.
2.	1400 kc	100 mmf.	Terminal No. 1	Manual B.C. Gang set at 1400 kc.	(A) Oscillator trimmer C42 on B.C. osc. coil T10 under chassis. (B) R.F. Trimmer C12 on R.F. coil T4 under chassis. (C) Ant. trimmer C1, on Ant. coil T13 on top of chassis. Gang to be rocked during (B) & (C) adjustment.
3.	600 kc	100 mmf.	Terminal No. 1	Manual B.C. Gang Set at 600 kc.	(A) B.C. concillator iron core on T10 on top of chassis. (B) R.C.R.F. iron core on top of chassis. (C) B.C. Ant. iron core on T13 under chassis. Gang to be rocked during (B) & (C) adjustment.
4.	1400 kc	Repeat No.	2 above		• • • • • • • • • • • • • • • • • • • •
5.	17.0 mc	400 ohms.	Terminal No. 1	Manual SW-1 Gang Set to 17.0 mc.	(A) SW-1 osc. trimmer C47 on osc. coil T12 under chassis. (B) R.F. trimmer C17 on bracket under chassis. (C) Ant. trimmer C5 on bracket on top of chassis.
6.	10.5 mc	400 ohms.	Terminal No. 1	Manual SW-1 Gang Set to 10.5 mc.	(A) SW-1 osc. iron core on T12 on top of chassis. (B) R.F. iron core on T3 on top of chassis. (C) Ant. iron core on T1 under chassis. Gang to be rocked during (B) & (C) adjustment.
7.	17.0 mc	Repeat No.	5 above		p.
8.	9.5 mc	400 ohms.	Terminal No. 1	Manual SW-2 Gang Set to 9. 5 mc.	(A) SW-2 osc. trimmer C46 on osc. coil T11 (B) R. F. trimmer C18 on bracket under chassis. (C) Ant. trimmer C6 on bracket on top of chassis. Gang to be rocked during (B) & (C) adjustment.
9.	6.0 mc	400 ohms.	Terminal No. 1	Manual SW-2	Adjust osc. iron core on T11 on top of chassis
10.	9.5 mc	Repeat No.	8 above	Gang tuned to signal	while rocking gang for maximum sensitivity.

## REALIGNMENT OF PRESET PUSH BUTTON CIRCUITS

Before shipping, Preset Push Button Circuits are tuned to 600 kc-s, 600 kc-s, 700 kc-s, 900 kc-s, 1200 kc-s, 1600 kc-s, in that order. To retune any one of them, (a) adjust iron core in Preset osc. coil until signal at desired frequency is heard; (b) adjust preset trimmer for max. output.