

The B&K 707 tube tester set up chart for the ECC808 (6KX8) tube has incorrect selector switch positions for switch D, the correct switch D positions are shown below. This error may also apply to other B&K tube tester models.

TUBE TYPE	HEATER	SOCKET	SENSITIVITY	A	B	C	D	TEST POS.
				ECC808	6	39	33	
			33	5	4	12	<del>7</del> 9	1

The 707 tube chart on our web site has been updated