



NOTE  
 FILAMENT SWITCH IN + LEAD FOR CONSOLE MODEL.  
 do do IN - do do TROUBLE do do

10	2 MFD. HYDRA		
9	1 MFD. --"		
8	1 MFD. --"		
7	.002 MFD. ELECTRAD		
6	5" N°22 TINNED COPPER BELL WIRE	6	.45 OHM FIXED MARCONI
5	.00025 MFD. ELECTRAD	5	3 MEG ELECTRAD GRID LEAK
4	.00028 MFD. MARCONI	4	5 OHM MARCONI RHEOSTAT
3	--"	3	675 OHM FIXED MARCONI
2	--"	2	--"
1	--"	1	--"
<b>CONDENSERS</b>		<b>RESISTANCES</b>	

**21976**

MARCONI XI  
 RECEIVER

CANADIAN MARCONI COMPANY LIMITED

DRAWN BY: *[Signature]*  
 CHECKED BY: *[Signature]*  
 DATE: MAY-11-28

USED ON: \_\_\_\_\_ REQ. TYPE NO. \_\_\_\_\_

Issue - 2 - JUNE 20th 1928.  
 3 - AUG - 17 - 1928