

Television and Radio Service Bulletin

GENERAL MERCHANDISE OFFICE

Insert NOW in
Radio Service Manual
as: Data Sheet No.

KITCHENER

July 21, 1959

5Y3G FAILURES

RC 308, RC 308R, RC 355, RC 361, RC 367

In order to increase the life of the 5Y3G rectifier in the above models, a 100 ohm ten watt resistor may be added in series with the B plus line. The addition of a three amp fuse in the primary circuit of the power transformer is also desirable as an added safety feature. The parts required as listed below are available from our Service Department free of charge upon request.

1 - 42-1-51 ----- 100 ohm 10 watt resistor
1 - 34-50-01 ----- fuse holder
1 - 31-260611-06 - screw
1 - 33-25-02 ----- washer
1 - 27-6-06 ----- fuse

All remaining stock of the RCS 361 will be reworked prior to shipment.

Yours very truly,

Dominion ELECTROHOME Industries Limited



D. Kehn
Supervisor, Field Service

DK/js