

# Television and Radio Service Bulletin

---

GENERAL MERCHANDISE OFFICE

Insert NOW in  
Radio Service Manual  
as: Data Sheet No. ....

KITCHENER

October 27, 1958

## STEREO CONVERSION

RCS 361, RCS 308R, RCS 355

In order to prevent oscillation due to common grounds on speaker leads, the following changes must be made during stereo conversion:

### RCS 361

- (a) Remove back.
- (b) Remove ground from right hand speaker.
- (c) Connect separate ground wire from this speaker to second channel amplifier. Route wire through hole behind chassis.

### RCS 308R, RCS 355

- (a) Disconnect ground wire from chassis output strip.
- (b) Remove jumper between terminals three and four.
- (c) Remove jumper between terminals four and five.
- (d) Add jumper between three and five.
- (e) Connect ground wire between terminal three and ground on chassis strip.

NOTE: In all cases above, the ground must be reconnected if monaural facilities of both speakers is required.

Yours very truly,

Dominion ELECTROHOME Industries Limited



D. Kehn  
Service Manager

DK/js