

Television and Radio Service Bulletin

GENERAL MERCHANDISE OFFICE

Insert NOW in
Radio Service Manual
as: Data Sheet No.

KITCHENER

July 31, 1959

RMK 369 - RM 368

PARTS LIST

The following errors have been noted in manual 54-433-01 for the above models. Please adjust your records accordingly.

<u>Part Number</u>	<u>Description</u>	<u>Remarks</u>
21-414-01	IF Transformer 1st and 2nd	Used on RMK 369 only.
21-432-01	IF Transformer 1st and 2nd	Used on RM 368 only. (Not listed on manual).
21-428-01	BC Interstage Coil	Used on RM 368 only. (Listed in error as 31-428-01).
44-27-04	Electrolytic	Part number shown on manual as 41-27-04 in error.
44-6-09	Electrolytic	Part number shown on manual as 41-6-09 in error.

Yours very truly,

Dominion ELECTROHOME Industries Limited



D. Kehn
Supervisor, Field Service

DK/js