


GM and EM Ultra - Fast TUBE TESTER



ALL RESISTORS ARE 1/2 WATT
UNLESS OTHERWISE SPECIFIED
K = 1000 OHMS, M = 1,000,000 OHMS

IS NOT CHASSIS
BUT BUS BAR

Precise
MODEL 116