



POS N°	FUNCTION
1	OPEN
2	800VAC
3	160VAC
4	40VAC
5	8VAC
6	3VAC
7	1.6A
8	160MA
9	16MA & 16A
10	1.6MA
11	160µA
12	16µA
13	R X 1
14	R X 10
15	R X 100
16	R X 1K
17	R X 10K
18	R X 100K
19	1.6VDC
20	8VDC
21	40VDC
22	160VDC
23	400VDC
24	1.6KVDC & 4KVDC

SW VIEWED FROM FRONT  
IN OPEN POS

# Simpson 269 V.O.M.

Model 269 Multimeter. D.C. Voltages are measured with a sensitivity of 100,000 ohms per volt.