



ALTERNATION NUMBER 100-522 W

RESISTORS R34 AND R47 ARE CALIBRATION RESISTORS WHOSE VALUE IS DETERMINED DURING THE CALIBRATION OF THE INSTRUMENT.
 R34 - 7500 Ω APPROX.
 R47 - 1500 - 7500 Ω APPROX.

"STARK" MODEL TA-1 "VOHMASTER"

STARK ELECTRONIC INSTRUMENTS LTD.			
TORONTO CANADA			
MODEL TA-1 SCHEMATIC			
4-1-47	4-3-47	4-4-47	DATE
OWN	CHK'D	APPROVED	SCALE
PART NUMBER		SIZE	
<i>W. J. Adams HMC</i>			