

# Television and Radio Service Bulletin

---

GENERAL MERCHANDISE OFFICE

Insert NOW in  
Radio Service Manual  
as: Data Sheet No. ....

KITCHENER

February 29, 1960

RCS 405 - RCS 407 - RCS 414

The modifications to correct modulation hum and improve FM stability as outlined in our February 10 bulletin on the RCS 426 will also apply to the models RCS 405, RCS 407 and RCS 414.

Please adjust your records accordingly.

Yours very truly,

Dominion ELECTROHOME Industries Limited



D. Kehn  
Supervisor, Field Service

DK/js