



SEMI ADJUSTS R5, R7 AND R9 ARE FACTORY SET AND SOLDERED IN POSITION - DO NOT ATTEMPT TO ADJUST STARK 9-55 (LATER VERSION)