

CLAIRTONE SOUND CORPORATION LIMITED  
Toronto New York Chicago Los Angeles

Ref: SB-3-3A

November 1962

You may receive complaints from various customers on high frequency hiss on FM stereo, and outlined below are the field fix modifications which should be performed in order to satisfy these customers.

Model: C-303  
C-403

Modification: Increase de-emphasis by adding capacitors as shown in the diagram below. Both the 560 mmf and 1000 mmf capacitors should be added.

